





Alliance Fan Clutches

Optimized fan clutch replacement or repair. Optimal price.

Cost-competitive but manufactured to exact OEM specs.

Sophisticated engine cooling technology, but at an affordable price point.

Alliance fan clutches and rebuild kits get trucks back up and running faster, and keep engines cool more efficiently for longer.

Visit manufacturer's website (https://www.hortonww.com/on-highway.html)



Product Highlights



Pre-assembled components enable fast and easy installation.

Designed, built, and tested to OE specifications.

Fan engagements are smooth, preventing excessive wear to belt and belt tensioner.

Manufactured using high quality components for a long and reliable life.

DOWNLOAD CROSS REFERENCE POSTER >

PALLIANCE **ALLIANCE FAN CLUTCH PRODUCT GUIDE** Description Type of Part Key Features / Differentiators Dual pilot for Freightliner, PACCAR applications, Alliance and Horton OE are 100% the same part Most Borg Warner On/Off Clutch Head. ABP N20 9908504 K32/Kysor K32, 2.56 & 5 Pilot **Dual Pilot** 2.56" & 5" Fan pilots Dual pilot, On/Off, 2 single row standard bearings, spacers, Kit assembly (Ref Horton 15-DP, install included spacers to make 15-DP-L) Repair Kit, Dual Pilot Kit Assembly On/Off Replacement Kit for all Horton DMA On/Off drive ABP N20 795568N Spring Engaged Kit Assembly, 9.5 Friction disk and liner, Rebuild Kit, HTS Air Kit Assembly, ABP N20 9500HP Repair Kit HTS Dual pilot, 2-Speed, 2 single row standard bearing, spacers, Kit assembly Rebuild Kit, DMA Replacement Kit for DMA ABP N20 795582 Repair Kit Kit, 2-Speed Spring Engaged Hub Bearin 2 Single row bearings for Borg Warner drive hub Borg Warner drive hubs per application ABP N20 858101 Kit, KS Pulley Bearing Bearing Kit Borg Warner Rebuild Kit, S-type 7.5 Complete Kit Assembly S Type ABP N20 7500HP Repair Kit Kit Assembly, 7.5 Friction disk and liner S-Type Fan Clutch Seal Kit Seal Kit HTS & S Type ABP N20 4205 Seal Kit Seal Kit for all HTS & S type fan drives Dual pilot, On/Off, 30mm (short) DRAC, spacers, Kit assembly (Ref Horton IS-OP-S) Fan Clutch Kit, DM 2.56 ABP N20 795669 Repair Kit MB, CAT engines primarily On/Off Seal Kit, DMA Spring All DMA On/Off & 2-Speed ABP N20 14S Seal Kit Seal Kit Kit for DMA On/Off & 2-Speed All Kysor K32 applications, can replace on the truck (no removal) Kit, KS K26 K32 Seal Kit Friction Liner & Seal ABP N20 88005KL Kysor K32, 2-piece friction liner & Seals and Lining Fan Clutch Kit, Remanufactured HT/S Reman HT/S Fan Clutch Reman HTS On/Off 9.5° Friction disk, Reman, air engaged, fail off ABP N20 91065R

DTNAParts

Repair Kit Cross Reference



ALLIANCE	Kit Master Kit	Part # Quick Kit	Part # Super Kit	Super Kit Description	Comments
ABP N20 795568N	14-256	Q995568	995530	DMA Super Kit (DRAC)	Quick Kit Replacement
	14-256	N/A	995567	DMA Super Kit (Long DRAC)	Replace 61 mm DRAC with 2 Single Row Bearings
	14-500	N/A	995607	DMA Super Kit (5.00" Pilot DRAC)	No Quick Kit
	14-500	N/A	995608	DMA Super Kit (5.00" Long DRAC)	Replace 61 mm DRAC with 2 Single Row Bearings
	14-256	Q995568	995568	DMA Conv Super Kit (DRAC)	Quick Kit Replacement
	14-256	Q995575	995575	DMA Conv Super Kit (Long DRAC)	Replace 61mm DRAC with 2 Single Row Bearings
ABP N20 795669	14-256-1	Q995669	994353 - OBSOL	DM & DMA Super Kit (Short DRAC)	Quick Kit Replacement (30 mm DRAC)
	14-256-1	Q995669	995669	DM & DMA Super Kit (Short DRAC)	Quick Kit Replacement (30 mm DRAC)
ABP N20 795582	24-256	Q995582	995582	DMA Two-Speed Super Kit (2.56" Pilot DRAC)	Quick Kit Replacement (39 mm DRAC)
	24-256	N/A	995543	DMA Two-Speed Super Kit (2.56" Pilot - No Bearing)	No Quick Kit w/ o Sheave Bearings
	24-256	Q995617	995617	DMA Two-Speed Super Kit (5.00" Pilot Long DRAC)	Quick Kit Replacement (39 mm DRAC)
	24-256	Q995617-L	N/A	DMA Two-Speed Super Kit (5.00" Pilot Long DRAC)	Replace 61 mm DRAC with 2 Single Row Bearings
	24-256	N/A	995547	DMA Two-Speed Super Kit (5.00" Pilot - No Bearing)	No Quick Kit w/ o Sheave Bearings
3	4	6	11	Total # of Part #'s to Support Market	

(6

FAN CLUTCH REPAIR KITS

CROSS REFERENCE

Alliance™ Parts	Kit Master Kit	Horton Quick Kit	Horton Super Kit
	14-256	Q995568	995530
	14-256	N/A	995567
	14-500	N/A	995607
ABP N20 795568N	14-500	N/A	995608
	14-256	Q995568	995568
	14-256	Q995575	995575
ABP N20 795669	14-256-1	Q995669	994353 - OBSOL
	14-256-1	Q995669	995669
	24-256	Q995582	995582
	24-256	N/A	995543
ABP N20 795582	24-256	Q995617	995617
	24-256	Q995617-L	N/A
	24-256	N/A	995547
Total # of Part #'s to support market 3	4	- 6	n

Alliance™ Parts	Kit Masters	Horton
ABP N20 4205	4205	994370
ABP N20 9500HP	9500HP	994305
ABP N20 7500HP	7500HP	994307
ABP N20 795568N	14-256, 14-500	995568, Q995568, Q995575, 995530, 995567, 995607, 995608, 995575
ABP N20 795669	14-256-1	Q995669, 995669
ABP N20 795582	24-256	995582, Q995582, 995543, 995617, 995547, Q995617, Q995617-L
ABP N20 9908504	8801X, 8801N, 8901N, 8905N, 1090-09650-01, 1090-09750-01	9908504









WHEN A COMPLETE FAN DRIVE ASSEMBLY IS NOT AVAILABLE AND YOU NEED TO SAVE MONEY ON ALL MAKES, USE ALLIANCE™ PARTS REPAIR KITS.

In 2021 Horse Handing to, all lights reason

Alliance Part Number (ABP N20 9908504)
NBP N20 8901N
090-09500-01
090-08500-03
090-08500-01
090-09500-01B
090-09650-01B
090-09900-01B
090-09900-01
090-09950-01B
090-09750-01B
090-09750-01

1090-09650-01B
1090-09600-01B
1090-09600-01
1090-09650-01
6514-070-1
65140701
3415013
3915592
2514343C91
2509380C91
2602141C91
8805X
8905N
8901X
8901N
8801X
8801N
8801
85134489
85111808
85114233
85108716
85134489

K32 Cross References

One part to make up for multiple parts. Refer to the chart to learn how the K32 Fan Drive covers multiple fan drive options.



Top Movers - Fan Clutch Rebuild Kits

PART NUMBER	DESCRIPTION
ABP N20 9908504	FAN CLUTCH, KS REAR AIR K32, DUAL FAN PILOT
ABP N20 795568	REBUILD KIT, HS SPRING ENGAGED, ON-OFF, TWO-BRGS, DUAL FAN PILOT
ABP N20 9500HP	REBUILD KIT, HS AIR ENGAGED 9.5
ABP N20 795582	REBUILD KIT, HS SPRING ENGAGED, TWO-SPEED, TWO-BRGS, DUAL FAN PILOT
ABP N20 858101	REBUILD KIT, KS PULLEY BEARING



General Product Information

Quality, cost-effective fan clutch replacements and repair kits, made to Original Equipment Manufacturer specifications.

The right torque

Alliance fan clutch repair solutions use OEM-specified torque levels — no abrupt engagements or extreme torque that wear out belts, tensioners and shorten fan clutch life.

Performance and value

Alliance rebuild kits are a cost-effective solution that use high quality components such as bearings with Viton® seals, steel cages and high-heat resistant grease.

Universal fit

Alliance fan clutch rebuild kits feature the lowest number of SKUs to cover the widest range of heavy-duty truck makes, models and years.

Warranty Information

100,000 mile/1 year warranty

Last updated: Tuesday, 28 November 2023 05:40 PM

∧Back to Top

 $\label{lem:copyright} \begin{tabular}{l} \textbf{Copyright} @ Daimler Truck North America LLC. $\underbrace{Privacy Statement, Legal Notices and Terms (https://daimler-trucksnorthamerica.com/privacy-policy).} \\ \textbf{Privacy Settings} \\ \end{tabular}$

All rights reserved. Daimler Truck North America LLC is a Daimler Truck North America LLC is a Daimler.com/) company.